

FIG. 2




FIG. 3





FIG. 4







FIG. 6



TOYUN 405 ... BUSGS




FIG. 8

### **LOCOMOTIVE CITY/STATE PROXIMITY**

LOS ANGELES

CII. STATE:

S

RANGE:

100 MILES

### **SEND QUERY:**

SUBMIT

# **ALL LOCOMOTIVES WITHIN 100 MILE RADIUS OF LOS ANGELES, CA**

LOCATION	1.9 MILES E OF CARSON, CA	1.9 MILES N OF MIRA LOMA, CA	1.3 MILES NW OF PEDLEY, CA	
LOCOMOTIVE	8618	8444	8350	

FIG. 9

GE TRANSPORTATION	
MY SERVICES	HELP   PERSONALIZE   LOGOFF
HOME MONITOR BOARD	BEST PRACTICES
PERSONALIZE THIS PAGE	GETS SERVICES PORTAL: MY PAGE
CHOOSE GADGETS	MY DOCUMENTATION
CHANGE LAYOUT	TROUBLE SHOOTING GUIDES
CHANGE COLORS	DASH 8 TROUBLESHOOTING GUIDE DASH 9 TROUBLESHOOTING GUIDE 202
ROAD NUMBER NAVIGATOR	
	FMI'S
SEARCH	24 3520 FMI CDC MODIFICATION
ADVANCED SEARCH	24 3643 FMI CCBII FILTER MODIFICATION
SAVED SEARCHES	24 3661 FMI CCBII PLUG INSPECTION
STATES OF MONEO	26 3711 FMI FUSE ELIMINATION
OCOMOTIVE TOOLBOX VER. 1.4	27 3473 FMI WATER TANK PRESSURE RELIEF VALVE
	27 3728 FMI RADIATOR CAP REMOVAL
SOFTWARE UPLOADS AND FAULT CODE DOWNLOADSSEE HOW IT'S DONE!	29 3700 FMI INJECTOR HOLD DOWN STUDS
DOWNLOADSSEE FIOW 11 3 DOINE!	30 3675 FMI WPS SENSOR REPLACEMENT
BEGIN	31 3723 FMI HEADLIGHT RESISTOR MODIFICATION
	32 3412 FMI TOILET MODIFICATION
OUL ANALYSIS SEARCH	33 3278 FMI BRAKE LEVER CHANGEOUT
TEP 1:	SPECIAL PROCEDURES
ELECT TYPE OF LOCOMOTIVE  ODASH8 DASH9	BATTERY RELATED CHECKS
OAC4400	BOSCH TOOLBOX RECORDING PROCEDURE
TEP 2:	CCBI UNITS HOW TO SET FLOW FOR A M61
YPE WORD OR FAULTCODE TO	CCBII UNITS HOW TO SET FLOW FOR A M61
SEARCH	CHECKING OVERSPEED 700 UP PHONEIX
SEARCH	CHECKING OVERSPEED B60 1123 UNITS NON PHONEIX
DVANCED SEARCH	○ CW 44 BOSCH EGU TOOLBOX READINGS
DIVITOLD GLI WIGHT	CYLINDER CUTOUT USING THE BOSCH TOOLBOX
AVED SEARCHES	DISARM 2 WAY EOT
	<u> → HOW TO LOAD CAB FILES</u>
ISTRUCTIONAL MATERIAL	
	AIR FLOW METER CALIBRATION
SEARCH	DASH 7 CONTRACTOR EVALUATION
DVANCED SEARCH	QUANTUM EVENT RECORDER TEST SETUP
	TORQUE VALUES
AVED SEARCHES	□ DASH 8
	□DASH 9
ARTS CATALOG ELECTIVE	△ AC4400
ELECT ROAD NUMBER OF LOCOMOTIVE:	OFNEDAL OAFED (NEODLATIO)
ELLOT HOND HOWIDLIN OF EUCOMOTIVE.	GENERAL SAFETY INFORMATION
OAD NUMBER	TO SAFELY LOCK OUT TAG-OUT THE LOCOMOTIVE (MECHANICAL
NONE SELECTED 🔻	
	MECHANICAL / P&M SAFETY RULES
204	MILOHAMIOAL / I GINI SAI LI I NULES



GE TRANSPORTATION SYSTEMS

REV 0 84A207789

TROUBLESHOOTING GUIDE FOR BNSF DASH 8 LOCOMOTIVES

# TROUBLESHOOTING GUIDE

### FOR

## BURLINGTON NORTHERN SANTA FE (BNSF) DASH 8 LOCOMOTIVES

FIG. 11



### GE TRANSPORTATION SYSTEMS MY SERVICES

### **BEST PRACTICE SHARING**

HELP | PERSONALIZE | LOGOFF

HOME MONITOR BOARD

BEST PRACTICES

212

**BOSCH HP PUMPS** SEARCH:

SEARCH BY KEYWORD POSTED BY SCOTT MACDONALD ON THURSDAY, JULY 13, 2000

ADVANCED SEARCH STARTED TO TRACK HISTORY ON UNITS THAT HAVE FAILED FOR HP FAILURES. RESULTS TO DATE:

A LINIT 2567 - FAILED ON 6/26/00 FOR RIDING LOAD POT AS LOW AS 6%

VIEW REPLIES...

VIEW REPLIES ...

UNIT IN FOR INSPECTION 4/17/00. POST NEW MESSAGE:

**UNIT 2579** 

AT THIS TIME PWR PISTON GAP WAS 0.367 AND ALL PUMPS FIRING... NEW MFSSAGF

BEST PRACTICES:

POST BEST PRACTICE POSTED BY SAGAR PATEL ON THURSDAY, JULY 13, 2000

CLICK TO READ MORE... REPLY...

VIEW BEST PRACTICES PLEASE SHARE YOUR TROUBLESHOOTING EXPERIENCE ON UNIT 2579 WITH THE

> FIFI D SERVICE TEAM REPLY... VIEW REPLIES ...

BROWSE MESSAGES:

BY CATEGORY BY DATE

TM INSPECTION

POSTED BY SCOTT MACDONALD ON WEDNESDAY, JULY 12, 2000 WE DEVELOPED A NEW INSPECTION AND TRAINING PROCESS FOR ELECTRICIANS

WORKING ON TM CABLE GROUNDS. THE PROCESS CAN BE REVIEWED ONLINE AT... RECENT MESSAGES: REPLY...

7/11 PROBLEM1 7/10 PROBLEM2 7/10 PROBLEM3

CLICK TO READ MORE... WATER DUMP VALVES

POSTED BY STAN HAYS ON TUESDAY, JULY 11, 2000


A MAJOR RELIABILITY DRIVER ON THE DASH 8 FLEET IS FAILURES DUE TO

WATER DUMP VALVES.

A FAILURE MODE HAS BEEN IDENTIFIED AND THE VALVES WERE OVERHAULED. THIS INFO IS TO BE SHARED WITH OTHER BAILBOADS THAT USE THIS VALVE.

CLICK TO READ MORE ... REPLY ... VIEW REPLIES...

12/12 USER INTERFACE



PARKED ACCEL/DECEL

CITY IDLE

CRUISE

CRUISE

WEHICLE LOCAL CUSTOMER MODEL OEM

FIG. 14